B.R. No: **958/14-15, Date: 31/01/2015**

Inspection report for the work of : Pot holes filling, in Ward no.-12, in Shettyhalli Sub-Division

By

Sri. ***Manjunath.K.***

Inspection Report

Name of Work		**Pot holes filling in ward no 12 in Shettyhalli Sub-Division**
Est. Cost	:	**10.00 Lakhs**
B.R. No & Dated	:	**958/14-15, Date: 31/01/2015**
Agency	:	**M/S.Vinyas builder**
Bill Amount	:	**974789.00**
Date of Inspection	:	10-03-2016.
Observations & Conclusions	:	

The above said work "pot holes filling in ward no 12 in Shettyhalli Sub Div." was shown to me by the concerned A.E.

The work is inspected by me along with the concerned A.E. Sri Ravi.

The work done is satisfactory

Ravi. N.C.
AEW-12

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕರ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು-57.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Name of Work : **Pot holes filling in ward no12,Shettyhalli sub Division**

Ravi. N.K.
AE W-12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (ETC)
PUBLIC WORKS DEPARTMENT

Name of Work : **Pot holes filling in ward no12,Shettyhalli sub Division**

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Ravi. N.K.
AEW-12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ